

**DRAFT FINAL  
EXPANDED ENGINEERING EVALUATION/COST ANALYSIS (EEE/CA)  
FOR THE  
McLAREN TAILINGS SITE  
COOKE CITY, MONTANA**

Engineering Services Agreement DEQ/MWCB 401027  
Task Order Number 05

**Prepared for:**

Mr. John Koerth  
Montana Department of Environmental Quality  
Mine Waste Cleanup Bureau  
P. O. Box 200901  
Helena, Montana 59620

**Prepared by:**

Pioneer Technical Services, Inc.  
P.O. Box 3445  
Butte, Montana 59702

**May 2002**

**APPENDIX C**

**PHOTO LOGS**

**2001 PIONEER TECHNICAL SERVICES, INC.  
RECLAMATION INVESTIGATION**



Photo 1: Boring #1, view is toward the west. Impoundment dam is visible in left background.



Photo 2: Boring #2, view is toward the east. Borrow area for 1990 toe berm construction is in background.





Photo 3: Boring #3, view is towards the southeast. There is a cluster of monitoring wells in this area.



Photo 4: Boring #4, view is to the northwest. Northern end of impoundment dam is visible in left background.





Photo 5: Boring #5, view is towards the west. The impoundment dam is visible across the front of the trees.



Photo 6: Boring #6, view is towards the west.





Photo 7: Boring #7, view is towards the west with impoundment dam on the other side of the drill rig.



Photo 8: Boring #8, vies is the west.





Photo 9: Boring #9, view is to the south. Southern end of impoundment dam is visible at mid-photo to the right.



Photo 10: Flow from toe drain at southern end of impoundment dam.